



Announcement Regarding the Discontinuation of MOS IC Products

Thank you for using SANYO semiconductor products.
The following SANYO semiconductor products have been discontinued.
Please check this list carefully and contact your SANYO semiconductor sales representative if you have any questions.

1. Affected products

See the table “Affected products list” on the following pages.

2. Reason for discontinuation

Rationalization and unification of the product lineup.

3. Replacement products

None.

4. Date of Implementation

November 2010.

Please contact your SANYO semiconductor sales representative if you have any questions or need an technical documentation.

Affected products list

Affected products	Affected products	Affected products	Affected products
LC351016AT-70U	LC35V256EM-70W-E	LC82161-YB8-E	LC89055WHS-RA8-TLM
LC35256DM-70	LC35V256EM-70W-TE-L	LC82210-LA2	LC89055WHS-RA8-TLM-E
LC35256DM-70HS-TLM	LC35V256EM-70W-TLM-E	LC82210-LA2-E	LC89055W-RA8
LC35256DM-70-TLM	LC35V256ET-70W	LC82210LK-UA0	LC89055W-RA8-E
LC35256FM-55U	LC35V256ET-70W-E	LC82210LK-UA0-E	LC89057W-E
LC35256FM-55U-TLM	LC35V256ET-70W-TLM	LC82210LK-UA0P-E	LC89057W-VF4D-E
LC35256FM-70U	LC35V256ET-70W-TLM-E	LC82212-VA1	LC89057W-VF4-E
LC35256FM-70U-E	LC35W1000BTS-10UHS	LC82212-VD8	LC89153
LC35256FM-70UHG	LC35W1000BTS-10UHSLE	LC822173-TBM	LC89160-TB2
LC35256FM-70UHG-E	LC35W1000BTS-10UHSTL	LC82281-WF9N	LC89170M
LC35256FM-70UHG-TLM	LC35W256E-10W-GB-E	LC822821-YD7	LC89170MP-TLM
LC35256FM-70UHGTLM-E	LC35W256EM-10W	LC82282-XD1	LC89170MP-TLM-E
LC35256FM-70UHS	LC35W256ET-10W	LC82283-YG4	LC89170M-TLM
LC35256FM-70UHS-E	LC35W256ET-10WHS	LC82283-YG4-E	LC892171A-NE2
LC35256FM-70UHS-TLM	LC35W256ET-10WHS-TLM	LC82293-RD8	LC89217A-PJ1
LC35256FM-70UHSTLM-E	LC35W256ET10WHSTLM-E	LC82293-RD8-E	LC895199K-ND2HS
LC35256FM-70UQ	LC35W256ET-10W-TLM	LC82294-TW58A	LC895199K-ND2HS-E
LC35256FM-70UQ-TLM	LC35W256E-X1	LC82294-TW58A-E	LC895872-WB7-TLM-E
LC35256FM-70UQ-TLM-E	LC35W256G-X1	LC82295-TJ5	LC89587-UK1-E
LC35256FM-70U-TLM	LC70300W-E	LC822961-03M-Z2	LC898094X-VJ3I-TBM-E
LC35256FM-70U-TLM-E	LC70700W-E	LC822961SQ-03M-E	LC898094X-WC2N-TBM-E
LC35256FT-70U	LC74980W	LC822961WL-YK0-TBM-E	LC898100-TBM-GB-E
LC35256FT-70U-E	LC78641NE-D	LC822966-TBM-GB-E	LC898210D-TBM-H
LC35256FT-70UHG-TLM	LC78815MF-TE-L	LC822971-ZF0-TBM-E	LC898210-TBM-H
LC35256FT-70UHGTLM-E	LC78816MC-TE-L	LC822972-00E-E	
LC35256FT-70UHS	LC78817M	LC8230	
LC35256FT-70UHS-E	LC78817M-TE-L	LC82310-TJ8A	
LC35256FT-70UHS-TLM	LC78820-C	LC82310-TJ8AHS	
LC35256FT70UHSTLM-E	LC78866VP	LC82310-TJ8AHS-E	
LC35256FT-70U-TLM	LC7886M-TRM-E	LC82311-00W-E	
LC35256FT-70U-TLM-E	LC80101MP	LC82311-00W-NR-E	
LC35256F-X1	LC80101MP-TRM	LC82311-WK1-E	
LC3564BM-10-TLM	LC82101-W09	LC82311-WK1-NR-E	
LC3564CM-70U	LC82102-04	LC82400-TLM-E	
LC3564CM-70U-E	LC821022	LC82561-PB5C	
LC3564CM-70UHS-TLM-E	LC82102WA-04	LC82561-PB5C-E	
LC3564CM-70UQ	LC82103	LC850511-B	
LC3564CM-70UQ-E	LC821033	LC850511-B-E	
LC3564CM-70U-TLM	LC821033-E	LC850515	
LC3564CM-70U-TLM-E	LC821034	LC850515-A-E	
LC3564CM-70U-TLM-E#	LC821034-E	LC850515-E	
LC3564CT-70UHS	LC8213K	LC8904Q	
LC3564CT-70UHS-TLM	LC82151K-PG8	LC89051V	
LC3564Q-10	LC821521	LC89051VHS	
LC3564QMF-10	LC821522	LC89051VHS-TLM	
LC3564SM-10-TE-L	LC821522-E	LC89051VHS-TLM-E	
LC3564SM-85-TE-L	LC82161-00R-R-E	LC89051V-TLM	
LC3564SS-10MN	LC82161B-E	LC89052T-E	
LC3564ST-85-TLM	LC82161B-R-E	LC89052T-TLM-E	
LC35V256EM-70W	LC82161-E	LC89055WD-RA8	