



Product End-of-Life Notification

EOL Number: CE082602

Date*: June 27, 2008

Product Description & Replacement:

All Biometric FingerChip products and associated FingerChip Security Processor devices are being discontinued.

This EOL covers the following devices.

AT77C102B-CB01YV	FingerChip Sensor
AT77C102B-CB02YV	FingerChip Sensor
AT77C104B-CH08YV	FingerChip Sensor
AT77C104B-CB08YV	FingerChip Sensor
AT91SAM7FP105-MU-A	FingerChip Security Processor

There are no replacement parts available.

For questions regarding any other AT77 Biometric FingerChip products please contact your local Atmel sales team.

Reason for EOL:

Atmel is exiting the Fingerprint Sensor Business.

Last Time Buy Date: December 31, 2008

** All orders placed after the notification date are **non-cancellable** and **non-returnable (NCNR)**.*

Last Ship Date: June 30, 2009

Atmel Contact: pcnadm@atmel.com

Information provided herein is in connection with Atmel products and this information is provided "AS IS". Atmel assumes no responsibility for any errors that may appear in this document. No license, express or implied, by estoppel or otherwise, to any intellectual property rights is granted by this document. Except as provided in Atmel's Terms and Conditions of Sale for such products, Atmel assumes no liability whatsoever, and Atmel disclaims any express or implied warranty, including liability or warranties relating to fitness for a particular purpose, merchantability, or non-infringement of any patent, copyright or other intellectual property right. Atmel products are not intended for use in a product or system intended to support or sustain life which, if it fails, can be reasonably expected to result in significant personal injury. Atmel may make changes to specifications and product descriptions at any time, without notice.